



Faithfull Tire and Auto Service  
 837A 50th STREET EAST  
 Saskatoon SK S7K-3Y5  
 Phone: 306-952-3133 Fax: 306-952-3155  
 e-mail: jae@faithfulltire.com

|                             |
|-----------------------------|
| PAGE: 1                     |
| DATE: 21 Oct 13             |
| GST REG#: 803943836 RT 0001 |
| PST REG#:                   |
| <b>INVOICE</b>              |
| <b>IN023358</b>             |

**SOLD TO:**  
**GWA**  
**GRASSWOOD AUCTIONS**  
**Box 8128**  
  
**Saskatoon SK S7K 6C4**

**CONTACT:**  
**Kelly Minisofer**  
**MOBILE : 306 380-5255** **HOME:**  
**BUSINESS: 306 955-4044** **FAX :**  
**EMAIL : kminisofer@sasktel.net carladycck@gmail.com**

| COLOUR            | VEHICLE DESCRIPTION   | PLATE           | UNIT#       | TAG  | ODO IN   |           |
|-------------------|---|-----------------|-------------|------|----------|-----------|
|                   | 2005 Ford F250 Super Duty 3/4 Ton - Pickup SUPER DUTY 5.4 L 330 CID V8 SOHC 24 Valve  | 8 SOHC 24 Valve | UNIT 37     |      | 131559   |           |
| VIN               | VEHICLE OPTIONS   |                 |             | ADV  | ODO AUTH |           |
| 1FTNF21525EC68732 |   |                 |             | MB   | 131559   |           |
| TIME IN           | PROMISED  | TERMS           | GST EXEMPT# | P.O. | ODO OUT  |           |
| 10:32 AM          |   | Net 30 days     |             |      | 131559   |           |
| QTY               | ITEM/DESCRIPTION  | WARR            | LIST        | DISC | NET      | EXT.PRICE |
| 1                 | <b>VI [ ] Vehicle Inspection -Light Duty 21 Oct 13</b><br><i>82 Point Inspection. -Suspension, Brakes, Fluids, Saftey Lights and Battery AVR Test.</i><br>Tech KENT: Bench seat bottom damaged<br>Full Inspection<br>Repair Required<br>-- Road Test: Wipper Check/Fluid<br>-- Brakes: Parking<br>-- Electrical: Lights |                 | 80.00       |      | 80.00    | 80.00     |
| 0.3               | <b>LAB [ ] Replace Left front signal, left front corner marker, plate lamps... out 21 Oct 13</b><br>BULBS # :<br>-<br>Subtotals Tax out 80.00 Tax in 84.00 (Declined: Tax out 40.95 Tax in 43.00)<br>**Customer note: Further Diagnostic may be required  |                 |             |      |          | Declined  |
| 0.9               | <b>LAB [**] Replace Right Rear Parking brake Cable... siezed 21 Oct 13</b><br>Parking Brake Cable - Remove and Replace Rear; F250 Super Duty, F350 Super Duty; Rear, One Side; XL; XLT; King Ranch; Lariat  |                 |             |      |          | Declined  |
| 1                 | WPW 1651268<br>Parking Brake Cable<br>Subtotals Tax out 0.00 Tax in 0.00 (Declined: Tax out 235.36 Tax in 247.13)   |                 |             | 0    |          | Declined  |
| 1                 | SS<br>Shop Supplies   |                 | 8.40        | 0    | 8.40     | 8.40      |
| 1                 | <b>LAB [ ] WASH AND DELIVER 21 Nov 01</b><br>Thank you for your business.   |                 | 25.00       |      | 25.00    | 25.00     |

BILL TO:

**TERMS AND CONDITIONS**

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work done and materials supplied. I authorize you, your agents or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

Thank you for your patronage!!!! Signature: \_\_\_\_\_

|               |               |
|---------------|---------------|
| PARTS:        | N/C           |
| LABOUR:       | 105.00        |
| OTHER:        | 8.40          |
| SUB-TOTAL:    | 113.40        |
| GST/HST:      | 5.67          |
| PST:          | N/C           |
| <b>TOTAL:</b> | <b>119.07</b> |